



Technical data

		Material		
Main component		C9-12 isoparafin		
Property	Regulation	Value		
Storage		Cool and dry		
Packaging		can		
Odour		odourless		

Areas of application

Apply pro clima GLUMEX to the surface to be cleaned with a soft cloth and gently rub it in. After just a few minutes, the contaminant can be seen coming away from the surface. The contaminant can then be rubbed off using a rough material (e.g. steel wool or a brush). If any residues remain, this process can be repeated.

It is recommended to test the compatibility of GLUMEX with the surface to be treated on a non-visible area of the surface.

Supply forms

Art. no.	GTIN	Contents	Weight	Sales unit	Container
10161	4026639017185	0.4	0.575 kg	3	501

Advantages

Removes adhesive residues left behind by adhesive tapes and acrylate copolymers

Highly effective within minutes



The information provided here is based on practical experience and the current state of knowledge. We reserve the right to make changes to the recommended designs and processing or to make alterations due to technical developments and associated improvements in the quality of our products. We would be happy to inform you of the current technical state of the art at the time you use our products.

pro clima planning documentation. If you have any questions, please contact [pro clima Technical Support](https://proclima.com/service/ technical-support).

Further information about installation and design details is available in the

MOLL

bauökologische Produkte GmbH Rheintalstraße 35 - 43 D-68723 Schwetzingen Fon: +49 (0) 62 02 - 27 82.0 eMail: info@proclima.de

